

Home Report



Property address: Scapa Sands
Longhope
Orkney
KW16 3PA

Customer: Joanne Strutt

Customer address: Scapa Sands
Longhope
Orkney
KW16 3PA

Date of inspection: 30th November 2017

1. INFORMATION AND SCOPE OF INSPECTION

This section tells you about the type, accommodation, neighbourhood, age and construction of the property. It also tells you about the extent of the inspection and highlights anything that the surveyor could not inspect.

All references to visual inspection refer to an inspection from within the property without the need to move any obstructions and externally from ground level within the site and adjoining public areas. Any references to left or right are taken facing the front of the property.

The inspection is carried out without causing damage to the building or its contents and without endangering the occupiers or the surveyor. Heavy furniture, stored items and insulation are not moved. Unless identified in the report the surveyor will assume that no harmful or hazardous materials or techniques have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

Services such as TV/cable connection, internet connection, swimming pools and other leisure facilities etc. were not inspected or reported on.

Description	A detached bungalow with garden ground. The property is used for entirely residential purposes.
Accommodation	Sitting Room/Kitchen, Two (2) Bedrooms, Bathroom, Hall.
Gross internal floor area (m²)	The gross internal floor area of the property is approximately 61m ² .
Neighbourhood and location	The property is situated near Longhope in Hoy, which is one of Orkney's south isles. Basic amenities, including a shop and hotel, are available locally. Hoy is connected by a regular car ferry service to the Orkney mainland, where all the usual amenities are available.
Age	The property is understood to have been recently constructed.
Weather	The weather was cold with showers, following a period of changeable weather. The report should be read in context of these weather conditions.

Chimney stacks

There are no chimney stacks.

Visually inspected with the aid of binoculars where appropriate.

Roofing including roof space

Pitched timber framed roof structure with timber sarking boards, clad with fibre cement roof slates.

150mm thick polyurethane insulation to the ceiling joists.

Sloping roofs were visually inspected with the aid of binoculars where appropriate.

Flat roofs were visually inspected from vantage points within the property and where safe and reasonable to do so from a 3m ladder externally.

Roof spaces were visually inspected and were entered where there was safe and reasonable access, normally defined as being from a 3m ladder within the property. If this is not possible, then physical access to the roof space may be taken by other means if the Surveyor deems it safe and reasonable to do so.

Rainwater fittings

uPVC gutters and downpipes.

Visually inspected with the aid of binoculars where appropriate.

Main walls

External walls are constructed of a structural timber frame, with block-work outer leaf. The walls are finished externally with dry-dash; internally, the walls are strapped and lined with plasterboard.

Visually inspected with the aid of binoculars where appropriate. Foundations and concealed parts were not exposed or inspected.

Windows, external doors and joinery

Double glazed uPVC windows and external doors.

Internal and external doors were opened and closed where keys were available.

Random windows were opened and closed where possible. Doors and windows were not forced open.

External decorations

There are no external decorations.

Visually inspected.

SINGLE SURVEY

Conservatories / porches

There are no conservatories or porches.

Visually inspected.

Communal areas

There are no communal areas.

Circulation areas visually inspected.

Garages and permanent outbuildings

There are no garages or permanent outbuildings.

Visually inspected.

Outside areas and boundaries

Area of garden grounds surrounding the house.
Hard-cored driveway to the house from the public road.

Visually inspected.

Ceilings

The ceilings are lined with plasterboard.

Visually inspected from floor level.

Internal walls

The inside faces of the external walls are strapped and lined with plasterboard.
The partitions are of timber stud construction clad both sides with plasterboard.

Visually inspected from floor level.

Using a moisture meter, walls were randomly tested for dampness where considered appropriate.

Floors including sub floors

Solid concrete ground floor.

Surfaces of exposed floors were visually inspected. No carpets or floor coverings were lifted.

Sub-floor areas were inspected only to the extent visible from a readily accessible and unfixed hatch by way of an inverted "head and shoulders" inspection at the access point.

Physical access to the sub floor area may be taken if the Surveyor deems it is safe and reasonable to do so, and subject to a minimum clearance of 1m between the underside of floor joists and the solum as determined from the access hatch.

Internal joinery and kitchen fittings

4-panel pine internal doors with chrome lever handles; glazed door between Sitting Room/Kitchen and Hall.
Softwood skirtings and facings.
Plywood window cills with plasterboard ingoes.
Fitted floor and wall units to the Kitchen.
Plywood cupboard door in the Bathroom.

Built-in cupboards were looked into but no stored items were moved.

Kitchen units were visually inspected excluding appliances.

Chimney breasts and fireplaces

There are no chimney breasts or fireplaces.

Visually inspected. No testing of the flues or fittings was carried out.

Internal decorations

Walls and ceilings are emulsioned; woodwork is varnished.
Tiled splash-backs to the Kitchen units, and behind the bath and wash-hand basin in the Bathroom.
Vinyl floor coverings to most of the house, with floor tiles to the Bathroom.

Visually inspected.

Cellars

There are no cellars.

Visually inspected where there was safe and purpose-built access.

Electricity

The property is served by a mains electricity supply to distribution boards and single tariff meter in a meter cupboard in the Entrance Hall.

PVC sheathed cables to power and lighting circuits.

Smoke detectors fitted to the ceilings of the Sitting Room/Kitchen and Hall.

Extractor hood in the Kitchen; extractor fan to the Bathroom.

Accessible parts of the wiring were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the surveyor will state that in the report and will not turn them on.

Gas

There is no mains gas in Orkney.
Calor Gas supply to the cooker.

Accessible parts of the system were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the surveyor will state that in the report and will not turn them on.

Water, plumbing and bathroom fittings

There is a mains water supply to the property.
The pipework, where visible, is of copper and uPVC construction.
Sanitary ware includes:
Kitchen: stainless steel sink and drainer.
Bathroom: plastic bath with mixer shower above, wash-hand basin, WC.

Visual inspection of the accessible pipework, water tanks, cylinders and fittings without removing any insulation. No tests whatsoever were carried out to the system or appliances.

Heating and hot water

The property is heated by air to air heating, with internal units in the Sitting Room/Kitchen and Hall, electric panel heaters to the Bedrooms, an electric towel rail in the Bathroom, and an electric focal point heater in the Sitting Room.

Hot water is provided by a single electric immersion in the hot water cylinder, which is located in a cupboard in the Bathroom.

Accessible parts of the system were visually inspected apart from communal systems, which were not inspected. No tests whatsoever were carried out to the system or appliances.

Drainage

Drainage is understood to connect to a septic tank on site.

*Drainage covers etc were not lifted.
Neither drains nor drainage systems were tested.*

Any additional limits to inspection:

At the time of our inspection the property was occupied and fully furnished with floors fully covered throughout.


There was no access for inspection behind wall linings.

The drainage system was not open to inspection.

An inspection for Japanese Knotweed or other invasive plant species was not carried out.

Testing has not been carried out for naturally occurring Radon Gas.

Sectional diagram showing elements of a typical house



Reference may be made in this report to some or all of the above component parts of the property. This diagram may assist you in locating and understanding these terms.

2. CONDITION

This section identifies problems and tells you about the urgency of any repairs by using one of three categories.

Category 3	Category 2	Category 1
Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.
 Structural movement		
Repair category:	1	
Notes:	No significant defects noted.	
 Dampness, rot and infestation		
Repair category:	2	
Notes:	Some signs of condensation noted to window cills/ingoes.	
 Chimney stacks		
Repair category:	N/A	
Notes:	There are no chimney stacks.	
 Roofing including roof space		
Repair category:	1	
Notes:	No significant defects noted.	
 Rainwater fittings		
Repair category:	1	
Notes:	No significant defects noted.	
 Main walls		
Repair category:	1	
Notes:	No significant defects noted.	
 Windows, external doors and joinery		
Repair category:	1	
Notes:	No significant defects noted.	

SINGLE SURVEY

	External decorations
Repair category:	N/A
Notes:	There are no external decorations.
	Conservatories / porches
Repair category:	N/A
Notes:	There are no conservatories/porches.
	Communal areas
Repair category:	N/A
Notes:	There are no communal areas.
	Garages and permanent outbuildings
Repair category:	N/A
Notes:	There are no garages or permanent outbuildings.
	Outside areas and boundaries
Repair category:	2
Notes:	Garden areas are unkempt; paths are uneven and incomplete
	Ceilings
Repair category:	1
Notes:	No significant defects noted.
	Internal walls
Repair category:	1
Notes:	No significant defects noted.
	Floors including sub-floors
Repair category:	1
Notes:	No significant defects noted.
	Internal joinery and kitchen fittings
Repair category:	2
Notes:	Poor finish to internal joinery in places.

SINGLE SURVEY

	Chimney breasts and fireplaces
Repair category:	N/A
Notes:	There are no chimney breasts or fireplaces.
	Internal decorations
Repair category:	2
Notes:	Decoration is incomplete.
	Cellars
Repair category:	N/A
Notes:	There are no cellars.
	Electricity
Repair category:	1
Notes:	No significant defects noted. There is no evidence of recent testing and failure to service and test increases safety risks.
	Gas
Repair category:	2
Notes:	The Calor Gas bottles are on a temporary support which does not look stable.
	Water, plumbing and bathroom fittings
Repair category:	1
Notes:	No significant defects noted.
	Heating and hot water
Repair category:	1
Notes:	No significant defects noted.
	Drainage
Repair category:	2
Notes:	Pipework around the septic tank is untidy.

SINGLE SURVEY

Set out below is a summary of the condition of the property which is provided for reference only. You should refer to the comments above for detailed information.

Structural movement	1
Dampness, rot and infestation	2
Chimney stacks	N/A
Roofing including roof space	1
Rainwater fittings	1
Main walls	1
Windows, external doors and joinery	1
External decorations	N/A
Conservatories / porches	N/A
Communal areas	N/A
Garages and permanent outbuildings	N/A
Outside areas and boundaries	2
Ceilings	1
Internal walls	1
Floors including sub-floors	1
Internal joinery and kitchen fittings	2
Chimney breasts and fireplaces	N/A
Internal decorations	2
Cellars	N/A
Electricity	1
Gas	2
Water, plumbing and bathroom fittings	1
Heating and hot water	1
Drainage	2

Repair Categories

Category 3:

Urgent Repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.

Category 2:

Repairs or replacement requiring future attention, but estimates are still advised.

Category 1:

No immediate action or repair is needed.

Remember

The cost of repairs may influence the amount someone is prepared to pay for the property. We recommend that relevant estimates and reports are obtained in your own name.

Warning

If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions where the effect can be considerable.

3. ACCESSIBILITY INFORMATION

Guidance Notes on Accessibility Information

Three steps or fewer to a main entrance door of the property: In flatted developments the ‘main entrance’ would be the flat’s own entrance door, not the external door to the communal stair. The ‘three steps or fewer’ are counted from external ground level to the flat’s entrance door. Where a lift is present, the count is based on the number of steps climbed when using the lift.

Unrestricted parking within 25 metres: For this purpose, ‘Unrestricted parking’ includes parking available by means of a parking permit. Restricted parking includes: Parking that is subject to parking restrictions, as indicated by the presence of solid yellow, red or white lines at the edge of the road or by a parking control sign, parking meters or other coin-operated machines.

1. Which floor(s) is the living accommodation on?	Ground
2. Are there three steps or fewer to a main entrance door of the property?	Yes
3. Is there a lift to the main entrance door of the property?	No
4. Are all door openings greater than 750mm?	Yes
5. Is there a toilet on the same level as the living room and kitchen?	Yes
6. Is there a toilet on the same level as a bedroom?	Yes
7. Are all rooms on the same level with no internal steps or stairs?	Yes
8. Is there unrestricted parking within 25 metres of an entrance door to the building?	Yes

4. VALUATION AND CONVEYANCER ISSUES

This section highlights information that should be checked with a solicitor or licensed conveyancer. It also gives an opinion of market value and an estimated re-instatement cost for insurance purposes.

Matters for a solicitor or licensed conveyancer

Check

- Rights and responsibilities for mutual parts, shared fences etc.
- That the Title is clean and Heritable with no onerous burdens or conditions.
- Appropriate discharge consents have been obtained for the foul drainage system.

Estimated re-instatement cost for insurance purposes

£150,000 (One Hundred and Fifty Thousand Pounds)

Valuation and market comments

The market value of the property as described in this report is £80,000 (Eighty Thousand Pounds). This figure assumes vacant possession and that the property is unaffected by adverse planning proposals, onerous burdens, title restrictions and servitude rights.

Signed**Surveyors Name**

Billy Groundwater, AssocRICS

Company Name

Orkney Surveying Services

Address:

Castlehowe, Sower Road, Orphir, Orkney, KW17 2RE

Date of report:21st January 2018