



Generic Mortgage Valuation

Property Address -	17 Earl Thorfinn Street, Kirkwall, Orkney, KW15 1QF.
Seller's Name -	Erlend and Rhona Aim.
Lending Institution -	To be confirmed if applicable.
Date of Initial Inspection –	14th August 2019.
Date of Replacement Inspection -	28th October 2020.

Important Note: This form of valuation is carried out only to the instructions of and for the purposes of lending institutions to assist them in determining what advance if any may be made on the security of the property. Other forms of valuation or survey are available for prospective purchasers on which they can rely for their interest. A description of the type of valuation undertaken is provided on Page 2.

SERVICES INCLUDE:

Bank &
Building
Society
Valuations

Residential &
Commercial
Property Surveys

Single
Surveys

Energy
Performance
Certificates

SAP
Certifications

Building
Surveying
Services

Rental &
Insurance
Valuations

Residential
& Commercial
Plans

Title Deed
Plans

Overseeing
New Builds

Planning
& Building
Warrant
Applications

A list of partners is available at the above address

LOCAL KNOWLEDGE ■ NATIONAL COVERAGE

Offices throughout Scotland

Each member firm of First Surveyors Scotland is an independent entity and no partnership implies or otherwise exists between the firms by reason of their membership of First Surveyors Scotland. First Surveyors Scotland is the trading name of First Surveyors Scotland Limited a company registered in Scotland Company No 201050. Registered Office: 57 Albany Street, Edinburgh, EH1 3QY



GENERIC MORTGAGE VALUATION

Involving a restricted form of Inspection and Report
Purpose: To establish a value of the property for Mortgage purposes only.

INCLUSIONS

Main Building - External

To the extent that they are visible from ground level - roof coverings, chimneys, parapets, gutters, walls, windows, doors, pipes, wood or metal work, paintwork, damp proof courses and airbricks.

Main Building - Internal

Ceilings, walls and other load bearers, floor surfaces (except where covered) to the extent necessary to establish their apparent condition.

Cellars, if reasonably accessible, to the extent necessary to establish condition.

Decorations generally and sanitary and kitchenware, limited throughout to the identification of significant visible defects only.

Services

Means of soil and waste disposal, (main) gas, (main) electricity, (main) water, extent and type of central heating/hot water supply.

Outbuildings - External

Garages and other buildings of substantial permanent construction; any structure attached to the dwelling.

Boundary Structures

Site boundary fences, walls and structures to the extent necessary to establish their apparent stability.

EXCLUSIONS

Main Building - External

Any parts not readily accessible or visible including foundations and drains.

Main Building - Internal

The valuer is not expected to enter into the roof space unless alerted to a fundamental defect.

Any parts not readily accessible or visible.

Under-floor voids.

Suitability or otherwise for any particular purpose.

Services

Determination of age, efficiency or condition of installations unless obviously
(i) dangerous.
(ii) substantially defective.
(Note: Testing of the services listed opposite is excluded)

Outbuildings - External

All other structures and leisure facilities of every description.

Boundary Structures

Any disrepair that would not significantly affect the value of the security.
Drives, paths and gates.

I - This mortgage valuation has been undertaken in accordance with the R.I.C.S. Valuation Standards, Global and UK, as Amended.

II - The Mortgage Valuation is provided for lending purposes and for the sole use of the named Lender. It is confidential to the Lender, the applicant and his professional advisers and the Valuer accepts no responsibility whatsoever to any other person.

III - It is assumed that there is a valid title to the subjects free of any onerous encumbrances.

IV - A building survey has not been carried out nor have those parts of the property that are covered, unexposed or inaccessible been inspected. Such parts have been assumed to be in good repair and condition. It is not possible to express an opinion or give advice upon the condition of uninspected parts and therefore this Mortgage Valuation should not be taken as making any implied representation or statement about such parts.

V - An investigation has not been carried out to determine whether or not any deleterious or hazardous material has been used in the construction of this property, or has since been incorporated, and it is therefore not possible to state that the property is free from risk in this respect. For the purpose of this Mortgage Valuation it has been assumed that such investigation would not disclose the presence of any such material to any significant extent.

VI - No enquiries have been made concerning contamination affecting the property or neighbouring properties that would affect the valuation. However should it be established subsequently that contamination exists at the property or on any neighbouring land, or that the premises have been or are being put to any contaminative use, this might reduce the opinion of value provided.

Description –	Semi-detached single storey bungalow.
Accommodation –	Hallway, Living Room, Kitchen, Bathroom and 2 Bedrooms.
Gross external floor area (m²) –	77m ² .
Neighbourhood and location -	Situated in a Local Authority development, in a predominantly residential area within walking distance of Kirkwall town centre.
Age -	c.1950.
Tenure -	Absolute Ownership.
Construction	
Chimney stacks –	Shared concrete block chimney stack with concrete coping and 2no. pots. Visible leadwork where passing through the roof. Ownership and maintenance responsibilities for the stack should be confirmed.
Roofing including roof space –	Pitched roof clad concrete tiles on battens, felt, sarking boards and timber rafters. Fibreglass insulation laid between and over ceiling joists within roof space.
Rainwater fittings –	P.V.C. gutters and a combination of P.V.C. and cast iron downpipes.
Main walls –	Concrete block cavity walls, roughcast with visible evidence of previous cavity fill.
Windows and doors –	Windows are a combination of double glazed u.P.V.C and timber. u.P.V.C double glazed external doors.
Interior –	Ceilings are lined plasterboard. Internal walls and solid partitions are lined hardwall plaster.
Floors -	Suspended timber floors.
Heating –	Oil fired boiler to radiator central heating system. Solid fuel stove to living room. Heated towel rail to bathroom.
Services –	Mains water, electricity and drainage.
Garages & Outbuildings –	2no. timber sheds.
Condition –	Where open to general inspection the property is in satisfactory condition.
Evidence of	
Subsidence -	No.
Flooding -	No.

Commercial Use -

No.

Comments –

The subjects are a suitable security for mortgage purposes.

Confirm:-

1. Site boundaries.
2. Woodworm treated and guarantee obtained.

**Reinstatement Value
for Insurance Purposes –**

£130,000.

Market Value –

One Hundred and Thirty Thousand Pounds, £130,000.

Signature of Surveyor,



Christopher J Omand, BSc (Hons),
Chartered Valuation Surveyor,
RICS Registered Valuer.